
100
Create an LGA membrane frame.
105
Create an LGA membrane with holes corresponding to the LGA contacts.
110
Affix the membrane to the frame.
115
Attach the frame with membrane to the LGA socket so that holes in the membrane align with corresponding LGA contacts.
120

Fig. 1



Fig. 2



Fig. 3



Fig. 4



Fig. 5